FEDERAL COMMUNICATIONS COMMISSION 445 TWELFTH STREET SW WASHINGTON DC 20554

MEDIA BUREAU AUDIO DIVISION

APPLICATION STATUS: (202) 418-2730 HOME PAGE: www.fcc.gov/mb/audio/ ENGINEER: CHARLES N. (NORM) MILLER

TELEPHONE: (202) 418-2767 FACSIMILE: (202) 418-1410 E-MAIL: charles.miller@fcc.gov

May 4, 2011

Paul R. Metcalfe Radio Greenville, Inc. Box 278 Greeneville, Tennessee 37744

Re: Radio Greeneville, Inc.

WIKQ(FM), Tusculum, Tennessee Facility Identification Number: 15518

Special Temporary Authority

Dear Mr. Metcalfe:

This is in reference to the request filed April 29, 2011, on behalf of Radio Greeneville, Inc. ("RGI"). RGI requests special temporary authority ("STA") to operate Station WIKQ with emergency antenna facilities pursuant to Section 73.1680. In support of the request, RGI states that the licensed tower and transmitter building were destroyed by a tornado on April 27, 2011. RGI states that the destruction of the licensed transmitter site was total, and that it is not possible to resume operations at that site. RGI requests STA for operation with an emergency antenna mounted on a nearby existing tower.

Section 73.1680 of the Commission's rules provides for operation with emergency antenna facilities following damage to authorized antenna systems, provided that an informal request for continued use of an emergency antenna is filed with the Commission within 24 hours. In particular, Section 73.1680(b)(2) provides that FM and TV stations may erect any suitable radiator, or use operable sections of the authorized antenna(s) as an emergency antenna.

Accordingly, the request for STA IS HEREBY GRANTED. Station WIKQ may operate with the following facilities:

Geographic coordinates:

36° 10′ 03″ N, 82° 50′ 10″ W (NAD 1927)

Channel

276 (103.1 MHz)

Effective radiated power:

1 kilowatt (H&V)

Antenna height:

above ground:

8 meters

above mean sea level:

503 meters

above average terrain:

8 meters

¹ WIKQ is licensed for operation on Channel 276A (103.1 MHz) with effective radiated power of 6 kilowatts (H&V) and antenna height above average terrain of -68 meters.

RGI must notify the Commission when licensed operation is restored. RGI must use whatever means are necessary to protect workers and the public from exposure to radio frequency radiation in excess of the Commission's exposure guidelines. *See* 47 CFR § 1.1310.

This authority expires on November 4, 2011.

STA Advisory: Section 309(f) of the Communications Act of 1934, as amended, authorizes the Commission to grant STA in cases of "extraordinary circumstances requiring temporary authorizations in the public interest and when delay in the institution of the temporary operations would seriously prejudice the public interest." However, Section 309(f) is not a means by which a licensee/permittee may circumvent established processing procedures which require the filing of an application, nor is it a means by which a broadcaster may enhance his facility or make operation more convenient for the broadcaster. Stations operating with less than licensed facilities under temporary authorities can be viewed as receiving the benefit of a larger protection area than that in which they are currently providing service.

Accordingly, Special Temporary Authorities by nature are to be temporary and are not intended for extended use. Licensees of stations operating under temporary authorities are reminded that timely restoration of permanent facilities is the responsibility of the licensee and should be undertaken expeditiously. Any request for extension of special temporary authorities carries an increased burden with each subsequent request.

Therefore, requests for extension of STA will be granted only where the licensee can show that one or more of the following criteria have been met:

- Restoration of licensed facilities is complete and testing is underway;
- Substantial progress has been made during the most recent STA period toward restoration of licensed operation; or
- No progress has been made during the most recent STA period for reasons clearly beyond the licensee's control, and the licensee has taken all possible steps to expeditiously resolve the problem.

Sincerely,

Charles N. Miller, Engineer

Audio Division Media Bureau

cc: Radio Greeneville, Inc.